# Lead-Safety Shopping List

# **EPA Lead Pamphlet**

• Renovate Right: Important Lead Hazard Information for Families, Child Care Providers and Schools

Currently Federal regulations require contractors to provide a copy of the *Renovate Right* pamphlet to owners and occupants prior to starting work in pre-1978 housing.

Contractors must also provide the *Renovate Right* pamphlet to owners and operators of child-care facilities and schools built prior to 1978 and provide information to parents or guardians of children under age 6 that attend.

To learn more about the requirements and how to obtain copies of the pamphlet contact the National Lead Information Center at **1-800-424-LEAD (5323)** or visit EPA's Web site at www.epa.gov/lead.

### **Tools and Supplies**

- Barriers and signs
- Tape
- Stapler
- Heavy plastic sheeting
- Utility knife or scissors
- Wet/dry sandpaper, sanding sponge
- Misting bottle, pump sprayer
- Chemical stripper
- Power tools with high efficiency particulate air (HEPA) filter-equipped vacuum attachments
- Low-temperature heat gun
- Heavy-duty plastic bags
- HEPA vacuum cleaner
- Paper towels or disposable wipes
- Mop and disposable mop heads
- General-purpose cleaner
- Buckets
- Shovel and rake

# Personal Protective Equipment

- Eye wear
- Painters' hats
- Gloves
- Coveralls
- Disposable shoe covers
- N-100-rated disposable respirator



EPA 740-F-08-001 March 2008

> Office of Pollution Prevention and Toxics United States Environmental Protection Agency Washington, D.C. 20460

To learn more about working safely with lead, contact the National Lead Information Center at 1-800-424-LEAD (5323) or visit EPA's Web site at www.epa.gov/lead.

Recycled/Recyclable Printed with Vegetable Oil-Based Inks on Recycled Pape (Minimum 50% Postconsumer) Process Chlorine Free



1-800-424-LEAD (5323) www.epa.gov/lead

# CONTRACTORS Lead Safety During Renovation



Awareness Program

As a contractor, you play an important role in protecting public health by helping prevent lead exposure. Ordinary renovation and maintenance activities can create dust that contains lead-even small amounts of lead can harm children and adults.

# **New Rules for Contractors**

Beginning April 2010 contractors performing work that disturbs lead-based paint in homes, child care facilities, and schools built before 1978 must:

- Be EPA certified, and
- Follow specific work practices to prevent lead contamination.

To learn more about how you can meet these requirements contact the National Lead Information Center at 1-800-424-LEAD (5323) or visit www.epa.gov/lead.

Be prepared for these new requirements. Adopt the following simple practices and you can work safely with lead.

# Talk to the Residents

- Explain the steps you will take to protect residents from lead:
  - Set up work areas that will not expose residents.
  - Minimize the dust.
  - Leave the work area clean.

When working in homes, child care facilities and schools built before 1978 you must provide the *Renovate Right* pamphlet to residents, or the facility operator before the job begins. You must also provide information to families whose children attend the child care facility or school.

# Set Up Safe Work Areas

#### Select Appropriate Personal Protective Equipment

- Review the lead-safety shopping list contained in this pamphlet to determine what items you need to safely perform the work.
- Ensure your workers have appropriate eyewear, clothing, and respiratory protection for the job.

The Work Area Should Be Contained So That No Dust Or Debris Leaves the Work Area.

# What To Do Inside:

- Use signs to keep residents and pets out of the work area.
- Remove furniture and belongings, or cover them securely with heavy plastic sheeting.
- Use heavy plastic sheeting to cover floors and other fixed surfaces like large appliances in the work area.
- When appropriate, use heavy plastic sheeting to separate the work area from the rest of the residence.
- Close and seal vents in the work area and, if necessary, turn off • forced-air heating and air conditioning systems.

# What To Do Outside:

- Mark off the work area to keep non-workers away.
- Cover the ground and plants with heavy plastic sheeting.
- Close windows and doors near the work area. •
- Move or cover play areas near the work area.

# Minimize the Dust

#### You Should Use Work Practices That Minimize Dust:

- Mist areas before sanding, scraping, drilling, and cutting.
- Score paint before separating components.
- Pry and pull apart components instead of pounding and hammering.
- Always use a shroud with HEPA vacuum attachment when using power tools and equipment.

#### **Do Not Use These Dangerous Practices** When Working With Lead-Based Paint:

- Open flame burning or torching.
- Sanding, grinding, planing, needle gunning, or blasting with power tools unless equipped with a shroud and HEPA vacuum attachment.
- Using a heat gun at temperatures greater than 1100°F.

### Leave the Work Area Clean On a Daily Basis You Should:

#### When the Job Is Complete, You Should Also:

- re-clean the area.

#### These Simple Practices Ensure That Your Jobs Are Better, **Cleaner, And Safer. Your Customers Will Notice The Difference.**

To learn more about working safely with lead and upcoming requirements, contact the National Lead Information Center at 1-800-424-LEAD (5323) or visit EPA's Web site at www.epa.gov/lead.



• Put trash and debris in heavy-duty plastic bags.

• Wrap waste building components, such as windows and doors, in heavy plastic sheeting and tape shut.

• Ensure everything, including tools, equipment, and even workers, are free of dust and debris before leaving the work area.

HEPA vacuum the work area.

• Wash up and change out of work clothes before you and your workers go home. Remember, you do not want to bring lead-based paint dust home and expose your family.

• Remind residents to stay out of the work area.

• Remove the plastic sheeting carefully, mist with water, fold dirty side in, tape shut, and dispose of it.

• HEPA vacuum all surfaces, including walls.

• Wash the work area with a general purpose cleaner.

 Check your work carefully for lead dust because hazardous amounts may be minute and not easily visible. If you see any dust or debris, then

• Perform a final clean-up check. Use disposable cleaning cloths to wipe the floor of the work area and compare them to a cleaning verification card to determine if the work area was adequately cleaned.

• To order a cleaning verification card and detailed instructions visit our website at www.epa.gov/lead or contact the National Lead Information Center at 1-800-424-LEAD (5323).

